			RTIFIC	- 1		
				ra-TE		
	of the Officer	:	DEA	E PUBL	1c 3cH	50L
2. Name	of the School	:		JGARA -	DORAT	シャナフ
 Location Sub Direction 	on with name of Edn.Dist./	.:	VEY	ngulam -	Molopp	wrams
in colur	ication of buildings as specifi nn 4 of the application for cortificate, and size	ied :	R CC Growd	Floor D to	66.00x =	f.50 mm
5. Period is issue	for which certificate	4		0 1× 0 1× 0 1×	3·06×4 6.00×6. 6.75×6.	20 mgr
6. Nature	of defects if any	:	0 85	21-27		
a) Fo	oundation and basement		20	4		
b) Su	perstructure	:	7			<i>2</i>
c) Do	eers and windows	:	- [sted dowing
d) Wo	ood work wrought and put up	· :	L ATE	deliest	e ans. W	ated and
e) Ro	of	n.	100	a Backing	, ,	
f) Fic	oring	:) 53	.9		
g) Mis	scellaneous (cracks etc)	:	F			
	or defects noticed which er the building unsafe anner		J			
	maintenance works have ne properly	:	403			~>
	the structure is sound conducting classes	:	parma	for cond	ucting to	state during
int	he stability of the structure s tensity of wind, exposure to f	lood etc.				O Conkulam Co
2. Any addition observations if Beemed necessary for the certificate may be furnished separately to with the certificate						
Certified ti	hat school ouisdipp was inspe					Pace Village *
2021-		THE PERSON NAMED IN		s for the period of/	academic year	
Peace Pu Place : O Venkulam, P.O.	ncipal blic Schran Corakan Kizhmuri OS 202)	ORAKAJBIGE Saction	1	Assistent LSGD S	katha _{er}	Manager, Peace Public Schoo Vengara
	Peace Public Sc Vengara	hool, ,				

FITNESS CERTIFICATE

To be filled by the Inspecting officer (Asst. Engineer) (Re: G.O. Ms. 20/70/PWD Dt.23-01-1970)

- 1. Name of the Officer
- 2. Name of the School
- 3. Location with name of Education District/Sub-District
- Classification of Building as specified in coloumn of the application for fitness certificate and size
- 5. Period for which the certificate is issued
- 6. Nature of defects, if any
 - a) Foundation and basement
 - b) Super structure
 - c) Doors and Windows
 - d) Wood work wrought and put up

: Assistant Executive Engineer, LID&EW, Vengara 8P

: Peace Public School, OK Muri, Venkulam

: Thirurangadi / Vengara

: RCC Framed Structure Building

:2021-22

New Building

Block 1 - 4x6.05x7.60-4 Room - FF

2x6.10x7.40 - 2 Room - FF

1x6.05x7.55 - 1 Room - FF

1x6.05x7.50 - 1 Room - FF

1x6.09x7.59 - 1 Room - FF

1x9.53x6.03 - 1 Room - FF

1x7.03x6.00 - 1 Room - FF

1x6.08x7.57 - 1 Room - FF

1x9.55x7.60 - 1 Room - SF

1x8.62x10.35 - 1 Room - SF 1X9.62x7.60 - 1 Room - SF

Block 2 - 3x6.00x6.00 - 3 Room - GF

1x7.70x6.00 - 1 Room - GF

2x6.35x5.85 - 2 Room - GF

1x5.50x3.00 - 1 Room - GF

1x4.10x3.00 - 1 Room -GF

1x4.50x3.55 - 1 Room - GF

1x4.50x6.00 - 1 Room - GF

3x6.00x6.00 - 3 Room - FF

1x7.70x6.00 - 1 Room - FF 2x6.35x5.85 - 2 Room - FF

1x5.50x6.20 - 1 Room - FF

1x4.45x6.00 - 1 Room - FF

Block 3 - 1x29.40x6.90 - 1 Hall- GF - GI Sheet with PVC sealing

- e) Roof
- t) Flooring
- g) Miscellaneous (Cracks, etc.)
- Any major defects noticed which will render the building unsafe in any manner
- Whether maintenance works have been done properly
- Whether the structure is sound or not for conducting classes

: Structure is sound for conducting Classes under normal weather and wind condition.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with this cerificate.

This fitness Certificate is Subjected to Court Order Obtained by the Principal, Peace Public School, Vengara

Certified that the school building was inspected by the on 23/10/2021 and round to be fit to conduct classes, for the period for the 2021-22 reasons stated above. Peace

Place: Vengara
Brien zigtogeb21
Peace Public School
Vengara
Venkulam, P.O. Oorakam Kizhmuri

Vengara

Vengara

Assistant Executive Engineer
LID& W Sub division
Vengara Block Panchayath.
ASSISIANT Executive Engineer
LSGD SUB DIVISION

Venkulan

ace Village

Block Panchayath Vengara